

	<p>Flange: <b>FL9037</b>            Gasket: GK9037</p> <p>Motor:</p> <table> <tr> <td>E1</td> <td>1071cc</td> <td>SOHC</td> <td>8V</td> </tr> <tr> <td>E3</td> <td>1296cc</td> <td>SOHC</td> <td>8V</td> </tr> <tr> <td>E5 + E5-T</td> <td>1490cc</td> <td>SOHC</td> <td>8V</td> </tr> </table> <p>L4 Mazda Motor</p>	E1	1071cc	SOHC	8V	E3	1296cc	SOHC	8V	E5 + E5-T	1490cc	SOHC	8V				
E1	1071cc	SOHC	8V														
E3	1296cc	SOHC	8V														
E5 + E5-T	1490cc	SOHC	8V														
	<p>Flange: <b>FL9047</b>            Gasket: GK9047</p> <p>Motor:</p> <table> <tr> <td>KA</td> <td>1298cc</td> <td>OHV</td> <td>8v</td> </tr> </table> <p>L4</p>	KA	1298cc	OHV	8v												
KA	1298cc	OHV	8v														
	<p>Flange: <b>FL9077</b>            Gasket: GK9077</p> <p>Motor:</p> <table> <tr> <td>S2</td> <td>2209cc</td> <td></td> <td></td> </tr> <tr> <td>XA</td> <td>2522cc</td> <td></td> <td></td> </tr> <tr> <td>XB</td> <td>2701cc</td> <td></td> <td></td> </tr> <tr> <td>HA</td> <td>2977cc</td> <td></td> <td></td> </tr> </table> <p>Diesel</p>	S2	2209cc			XA	2522cc			XB	2701cc			HA	2977cc		
S2	2209cc																
XA	2522cc																
XB	2701cc																
HA	2977cc																
	<p>Flange: <b>FL9099</b>            Gasket: GK9099</p> <p>Motor: CORTINA</p> <table> <tr> <td>TL16</td> <td>1593cc</td> <td>OHC</td> <td></td> </tr> <tr> <td>TL20</td> <td>1993cc</td> <td>OHC</td> <td></td> </tr> </table>	TL16	1593cc	OHC		TL20	1993cc	OHC									
TL16	1593cc	OHC															
TL20	1993cc	OHC															
	<p>Flange: <b>FL9102</b>            Gasket: GK9102</p> <p>Motor:</p> <table> <tr> <td>1100</td> <td>1098cc</td> <td>OHV</td> <td></td> </tr> <tr> <td>1300</td> <td>1298cc</td> <td>OHV</td> <td></td> </tr> <tr> <td>1600</td> <td>1599cc</td> <td>OHV</td> <td></td> </tr> </table> <p>Crossflow Head</p>	1100	1098cc	OHV		1300	1298cc	OHV		1600	1599cc	OHV					
1100	1098cc	OHV															
1300	1298cc	OHV															
1600	1599cc	OHV															

# FORD 4CYL



	<p>Flange: <b>FL9140</b> Gasket: GK9140</p> <p>Motor: 4 Reqd                      2000cc</p> <p>V4 Capri Motor</p>
	<p>Flange: <b>FL9149</b> Gasket: GK9149</p> <p>Motor: 1200                      1198cc OHV 1300                      1295cc OHV 1400                      1340cc OHV 1500                      1498cc OHV</p> <p>Non Crossflow</p>
	<p>Flange: <b>FL9183</b> Gasket: GK9183</p> <p>Motor: HL1.6CVH                      1596cc OHC</p> <p>RS1600 &amp; XR3i</p>
	<p>Flange: <b>FL9184</b> Gasket: GK9184</p> <p>Motor: ZH20                      1989cc DOHC 16V</p> <p>Zetec Motor</p>
	<p>Flange: <b>FL9237</b> Gasket: GK9237</p> <p>Motor: Lotus Escort</p>

	<p>Flange: <b>FL9271</b>          Gasket: GK9271</p> <p>Motor:          Zephyr Mk IV</p> <p>V4</p>
	<p>Flange: <b>FL9300</b>          Gasket:</p> <p>Motor:          116E                      1500cc OHV    8V</p> <p>Non Crossflow</p>
	<p>Flange: <b>FL9379</b>          Gasket: GK9379</p> <p>Motor:          240                      3964cc</p> <p>V8</p>
	<p>Flange: <b>FL9410</b>          Gasket:</p> <p>Motor:          Focus LR    1600cc + 2000cc DOHC</p> <p>L4            Duratec</p>
	<p>Empty technical drawing area.</p>